


Operating instructions. . . . . . . . . . . . . . . . . . pages 1 to 2

## Dimensions

All measurements in mm.









Special version for NSK protective collar

Tightening torque of the fixing screws, guard collar NSK 1 Nm ± 0.1 Nm





# Operating instructions Enclosure for surface mounting

## Mounting




In hygiene-sensitive applications, the assembly housing must be fitted with an offset angle of at least 3 in order to ensure that water and other liquids can run off.



Assembly must be carried out on a grease-free, level surface with suitable M5 cheese-head screws. In hygiene applications, it must be ensured that cleaning and inspection for damage can be carried out from all sides. As such, we recommend a clearance of at least 10 cm to other machine parts.

### **Enclosure for surface mounting**



i

Tightening torque for M5 fixing screws and earth connections 1.3 Nm ± 0.1 Nm.

## Key

A: Cover fixing screws with gasket

B: Enclosure cover

C: Earth connections

D: Cover gasket

E: Enclosure lower section


F: Floor seal

## Supply kit

A: Supply kit with 4x cover fixing screws with gasket

C: Earth connection supply kit comprising 6x washers, 3x serrated lock washers and 3x nuts







Tightening torque 1.3 Nm ± 0.1 Nm

## Maintenance



Only approved cleaning agents are permitted for cleaning. We would be happy to provide a list on request. Cleaning must not be carried out above 80 C. After cleaning, an inspection must be carried out from all sides to check for damage. Faulty devices/parts must be replaced immediately.

### K. A. Schmersal GmbH & Co. KG

Möddinghofe 30, D - 42279 Wuppertal Postfach 24 02 63, D - 42232 Wuppertal

Phone: +49 - (0)2 02 - 64 74 - 0
Telefax: +49 - (0)2 02 - 64 74 - 1 00
E-Mail: info@schmersal.com
Internet: http://www.schmersal.com





